



Gypsum board sheathing damage MUST be repaired (replaced) STUD to STUD prior to any roofing or air /vapor barrier being installed:



When the paper face is torn off, the roof adhesive or the air/vapor barrier will get sucked into the gypsum and not properly adhere.

The roofing & air/vapor barrier needs to be fully supported. Damaged sheathing or sheathing that the face material has been torn off is not proper support for the roofing or air/vapor barrier – this will cause failure.

Always review your sheathing prior to the installation of the roof or air/vapor barrier & always repair stud to stud.

