



When we have fire rated walls

The top and bottom tracks must run continuous. We cannot have the flanges cut out for MEP-FP items. Interior or Exterior framing...



*The systems were tested with a full flange installed...
To stop the passage of fire & smoke*



The flange(s) must be restored via framing angle or strapping- same gauge.

